




TRAY ROLLER ASSEMBLY

- It is important that these assemblies be aligned and secure.
- Shifting of roller assemblies can cause the cable to climb over sheave edge and cut the cable.
- All rollers to be free rolling to eliminate friction.
- Space tray rollers to minimize cable drag.
- Use greater bending radii than allowed.



Service Wire Company believes the information presented herein is, to the best of our knowledge, true and accurate based on currently available industry data. However no warranties, either expressed or implied, are made as to the accuracy or completeness of any information contained herein. Consequently, Service Wire Company makes no guarantee of the results and assumes no obligation or liability whatsoever in connection with this information.